

## **Region 3 GPRA Baseline RCRA Corrective Action Facility**

# **Wayne Div. Dresser Equip Group (Formerly: Dresser Industries, Inc.)**

**124 West College Avenue  
Salisbury, MD 21801  
Congressional District 1  
EPA ID #: MDD044147098  
Last Updated 6/15/05**

## **Current Progress at the Site**

---

This facility is one of EPA Region III's high priority RCRA corrective action sites. EPA has conducted an Environmental Indicator (EI) inspection at this facility and determined that RCRA Corrective Action is necessary. The facility has completed an environmental assessment of the onsite Benzene, toluene, ethylbenzene, and xylene contaminants and completed environmental sampling in September 2003. EPA has reviewed the facilities 2003 sampling data and requested additional data and description of the surrounding area. The facility has forwarded to EPA the background data supplemental information on the site and surrounding area to document the environmental indicator determination in April 2004. The supplemental information inconclusive sampling on the extent of contamination. EPA has received the Dresser December 2004 work plan to determine the source of the onsite contaminants. The workplan was approved in May 2005.

## **Site Description**

---

The Dresser facility has been at 124 West College Avenue, Salisbury, Maryland since 1938. In 2001, the facility ended its operations at the Salisbury, MD plant. The facility manufactured fuel pumps for both domestic and international markets. The Salisbury, MD facility is a RCRA generator and, from its production and painting processes as well as wastewater treatment facilities, Dresser managed various hazardous waste, including wastewater treatment effluent and sludge; spent solvents (equipment cleaning); paint based solid and sludge waste; waster corrosive liquid; sludge for metal pre-treatment and coating prior to electrostatic painting and volatile release; and, solvent stripped from silk screening process dryers, burn off ovens and powder paint ovens. In 2001, the facility closed and dismantled its Salisbury, MD operations, however it has not completed RCRA closure of its hazardous waste management activities.

## Site Responsibility

---

RCRA Corrective Action activities at this facility are being conducted under the direction of EPA Region 3 with assistance from the State.

## Contaminants

---

Various historical spills including waste oil, gasoline, mineral spirits, volatile organic compounds, and gasoline constituents have resulted in releases to air, soil, and groundwater at the facility. Remediation of the various releases have been conducted through EPA and the State of Maryland.

## Community Interaction

---

All final remediation activities will be subject to public participation.

## Institutional Controls

---

No institutional controls are currently in place.

## Government Contacts

---

EPA Project Manager  
Ms. Wanda Martinez - 3WC23  
U.S. Environmental Protection Agency - Region III  
1650 Arch Street  
Philadelphia, PA 19103-2029  
Phone: (215) 814-3434  
Email: butler.vernon@epa.gov

Mr. Amin Yazdanian  
Maryland Department of the Environment  
1800 Washington Blvd., Suite 645  
Baltimore, MD 21230-1719  
Telephone: (410) 537-3345  
Email: ayazdanian@mde.state.md.us

For more information about EPA's corrective action webpage, including Environmental Indicators, please visit our site at: [www.epa.gov/reg3wcmd/correctiveaction.htm](http://www.epa.gov/reg3wcmd/correctiveaction.htm)

## Facility Contact

---

Shen Wang, Ph.D., P.E.  
Senior Environmental Specialist  
Halliburton Company  
4100 Clinton Dr., 03-1106, Houston, TX 77020  
Phone (713) 676-8580, Fax (713) 676-7021